

कार्यालय कार्यपालन यंत्री
लोक निर्माण विभाग (भ./स.) संभाग क्रं.1 रीवा (म0प्र0)

Web site : www.mp.gov.in/pwmp

email :- cepwdlrewa@mp.nic.in Phone No. 07662-256858

पत्र क्रं. 6207 तक0/कार्य /2021-22

रीवा, दिनांक 31.12.2021

प्रति,

प्राचार्य,
डी पाउल स्कूल
मैदानी रीवा (म0प्र0)

विषय :- डी पाउल स्कूल बिल्डिंग का फिटनेस प्रमाण पत्र बावत्।

संदर्भ :- आपका पत्र क्रमांक DE PS/AH/2021-22/00 दिनांक 29.12.2021

उपरोक्त संदर्भित पत्र द्वारा डी पाउल स्कूल बिल्डिंग का सुरक्षा संबंधी प्रमाण पत्र प्रदाय हेतु अनुरोध किया गया है।


भवन का मौके से निरीक्षण कर प्रतिवेदन देने हेतु अनुविभागीय अधिकारी लोक निर्माण विभाग (भ./स.) उपसंभाग क्रं.1 रीवा को दिनांक 29.12.2021 द्वारा लेख किया गया है।

अनुविभागीय अधिकारी लोक निर्माण विभाग (भ./स.) उपसंभाग क्रं.1 रीवा एवं उपयंत्री द्वारा दिनांक 31.12.2021 को संयुक्त रूप से विषयांकित भवन का सुरक्षा संबंधी निरीक्षण कर प्रतिवेदन इस कार्यालय को पत्र क्रमांक 1149/तक/2021-22 रीवा दिनांक 31.12.2021 द्वारा प्राप्त हुआ है।


अतः अनुविभागीय अधिकारी से प्राप्त भवन सुरक्षा प्रमाण पत्र प्रतिहस्ताक्षरित कर आपकी ओर अग्रेषित है।

सहपत्र :- भवन का सुरक्षा प्रमाण पत्र।

कार्यपालन यंत्री
लोक निर्माण विभाग (भ./स.)
संभाग क्रं.1 रीवा (म0प्र0)



PRINCIPAL
De Paul School
Maidani, Rewa (M.P.)



MANAGER
De Paul School
Maidani, Rewa (M.P.)

OFFICE OF THE EXECUTIVE ENGINEER P.W.D (B/R) DIVISION NO.1
REWA (M. P)

Website: www.mp.gov.in/pwdmp
Phone – 07662 - 256858

E-mail- eepwd1rewa@mp.nic.in

FITNESS CERTIFICATE

To be filled by the Inspecting Officer

1. Name of the Officer: K. K. Garg Divisional Officer P. W. D (B/R)
Division No 1 Rewa.
2. Name of the School: DE PAUL SCHOOL
3. Location with name of Education District/ Sub. District:
Maidani, Tehsill Huzur, Distt. Rewa, M.P 486 001
4. Classification of Building as specified in column 4 of the
application for fitness certificate and size:
1. 867.843 SQM Built Up Area (Year – 2012)
2. 5232.157 SQM Built Up Area (Year-2016)
5. Period for which the certificate is issued: 2021 - 22
6. Nature of defects, if any:

- a) Foundation and basement: Not Applicable
- b) Superstructure: Not Applicable
- c) Doors and Windows: Not Applicable
- d) Wood work wrought and put up: Not Applicable
- e) Roof: Not Applicable
- f) Flooring: Not Applicable
- g) Miscellaneous (Cracks, etc.): Not Applicable

7. Any major defects noticed which will render the building unsafe in any manner: No

8. Whether maintenance works have been done properly: Yes

9. Whether the structure is sound or not for conducting classes: Building is sound and safe

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 31/12/2021 and found to be fit to conduct classes, for the period 2021 – 2022 for the reasons stated above.

Place: Rewa

Date: 29/12/2021


Sub Divisional Officer
P. W. D. (B/R) Sub Division No. 1
Rewa (M. P.)


EXECUTIVE ENGINEER P.W.D
(B/R) DIVISION NO.1
REWA (M. P)


Entd. No. 6207 / TS/2020-21/01.31/12/021
Copy forwarded to: Manager, De Paul School
Maidani, Rewa (M.P)

Rewa Dated 31/12/2021


PRINCIPAL
De Paul School
Maidani, Rewa (M.P.)


Sub Divisional officer
P.W.D. (B./R.) Sub Division No. 1
Rewa (M.P.)


Executive Engineer
P.W.D. B/R Dn.1 Rewa


MANAGER
De Paul School
Maidani, Rewa (M.P.)